

**UNIFORM HAZARDOUS  
WASTE MANIFEST**

1. Generator's US EPA ID No.

Manifest Document No.

2. Page 1

Information in the shaded areas  
is not required by Federal law.

3. Generator's Name and Mailing Address

BOEING REALTY CORP.

1060 LAKEWOOD BL. 5TH FLOOR LONG BEACH, CA. 90808-1700

4. Generator's Phone (562) 627-3078

5. Transporter 1 Company Name

J. CALIFORNIA

6. US EPA ID Number

CAD980814883

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

COPPER MOUNTAIN LANDFILL / AVE. 35E AND COUNTY 12TH ST.  
YUMA COUNTY, ARIZONA 85356

10. US EPA ID Number

AZCAP51206114

A. State Manifest Document Number

96603517

B. State Generator's ID

C. State Transporter's ID

D. Transporter's Phone

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

H. Facility's Phone

(520) 782-6355

11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

13. Total Quantity

14. Unit Wt/Vol

I. Waste Number

a. NON RCRA HAZARDOUS WASTE SOLID  
(SOIL CONTAMINATED WITH METALS)

001 PIT 00018 Y

State 611

EPA/Other N/A

b.

State

EPA/Other

c.

State

EPA/Other

d.

State

EPA/Other

J. Additional Descriptions for Materials Listed Above

11a. PROFILE # 12660

K. Handling Codes for Wastes Listed Above

a.

.03

b.

c.

d.

15. Special Handling Instructions and Additional Information

WEAR APPROPRIATE PROTECTIVE EQUIPMENT  
24 HR. EMERGENCY CONTACT: (800) 535 5053

SITE: 1414 DENKER ST.  
TORRANCE, CA.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

S.M. Stavale

Signature

SM Stavale

Month Day Year  
10 08 97

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

AT CLEARY

Signature

AT CLEARY

Month Day Year  
10 10 97

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

AZ NON HAZ

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

SHARON ROBERSON

Signature

SHARON ROBERSON

Month Day Year  
10 15 97

DO NOT WRITE BELOW THIS LINE.

Yellow: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS.  
(Generators who submit hazardous waste for transport out-of-state, produce completed copy of this copy and send to DTSC within 30 days.)